

knitter-switch

Discontinuation of Products

Products affected: MFS 131 DO SW slide-switch


Effectivity date: December 31, 2018

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFS 131 D is recommended.

knitter-switch, August 2018



Oliver Kluj

Technical Director