

knitter-switch

Discontinuation of Products

Products affected: MSP 131 C pushbutton switch


Effectivity date: Dezember 31, 2018

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MZP 1 C is recommended.

knitter-switch, August 2018



Oliver Kluj

Technical Director