

# knitter-switch

## Product Change Notice

Products affected:            DRR 60004, DRR 60004-1, DRR 60010, DRR 60010-1  
   DRR 60016, DRR 60016-1, DRR 60016-M  
   DRR 60104, DRR 60104-1, DRR 60110, DRR 60110-1  
   DRR 60110-1H, DRR 60116, DRR 60116-1  
   DRR 61010, DRR 61010-1, DRR 61016, DRR 61016-1  
   DRR 61110, DRR 61110-1, DRR 61116, DRR 61116-1


   DRS 60004-21, DRS 60010, DRS 60010-CH, DRS 60016  
   DRS 60016-CH, DRS 60110, DRS 60116, DRS 61010  
   DRS 61016, DRS 61110, DRS 61110-2.2, DRS 61116

   SMR 60010, SMR 60010-CT, SMR 60010 T, SMR 60016  
   SMR 60016-CT, SMR 60016 T, SMR 60110, SMR 60110 T  
   SMR 60116, SMR 60116 T, SMR 60216, SMR 60216-T-G13  
   SMR 61010, SMR 61010 T, SMR 61016, SMR 61016 T  
   SMR 61110, SMR 61110 T, SMR 61116, SMR 61116 T

Effectivity date:                    After current stock is sold out

### Details:

To prevent increase of delivery delay, switch position display and part number marking is changed from pad print to laser marking. This change is not affecting any other features or specification of the components.



Left hand side: pad print  
Right hand side: laser marking  
(rotor style for reference only)

knitter-switch - Baldham, October 2019

Oliver Kluj  
Technical Director