

# knitter-switch

## Product Change Notification

Products affected: DRS 3110, DRS 4110  
DRR 3110, DRR 4110  
SMR 5110, SMR 5110 T

Effective date: from next production lot

### Details:

The delivery position of the rotor will be changed from "0" to "7".

This measure improves the stability against soldering heat influence.

knitter-switch, November 2011



Oliver Kluj  
Technical Director