

knitter-switch

Product Change Notification

Products affected: TMP 1, TMP 1-1, TMP 1 R
TMPS 1, TMPS 1-1, TMPS 1 H, TMPS 1-1 H, TMPS 1 T
TMP 1 GF 600-W

Effective date: from date-code 1237 (week 37 in 2012)


Details:

For further improvement of the performance (endurance) the wall thickness of the actuator was reinforced.

This causes a change of the “plus” tolerances of the heights (case height, actuator height) from +0.1 mm to +0.15 mm.

Any other dimensions or tolerances as well as technical data or specification are not affected by this.

Knitter-switch, February 2013



Oliver Kluj
Technical Director