knitter-switch

Discontinuation of Products

Product affected:	ESP 1 D, ESP 1 D-RA ESP 1 F, ESP 1 F-RA
	ESP 2 D, ESP 2 D-RA ESP 2 F, ESP 2 F-RA

Effective date: after current stock is sold out

Details:

Due to bankruptcy of one of our subcontracting spare-part suppliers we are forced to remove these components from our range of products.

Our sales people will help you to find a replacement in another of our product lines.

We recommend considering TP 2-series or MPSA 22 E08-series (with momentary and latching function) and TSP-series (momentary only) for replacement.

knitter-switch, April 2009

Ohir allei

Oliver Kluj Technical Director