

# knitter-switch

## Product Discontinuation Information

Product affected: LD 70, LD 70-24, LD 70 S, LD 70 S-24  
LD 72, LD 72-24, LD 72 S, LD 72 S-24  
LD 96 G, LD 96 Y, LD 96 SG, LD 96 SR, LD96 SY

Effective date: immediately

### Details:

Semiconductors needed for these products are no longer available, therefore we stopped production.

Regarding replacement please contact your local sales person.

knitter-switch, September 2019



Oliver Kluj

Technical director