

knitter-switch

Discontinuation of Products

Products affected: MFP 102 D slide switch


Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, catalogue parts MFP 120 or MFP 113 D are recommended.

knitter-switch, February 2020



Oliver Kluj

Technical Director