

# knitter-switch

## Discontinuation of Products

Products affected: MFP 1370 slide-switch


Effectivity date: after stock is sold

### Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 1323 is recommended.

knitter-switch, November 2019



Oliver Kluj

Technical Director