

# knitter-switch

## Discontinuation of Products

Products affected: MFP 661 N slide-switch

Effectivity date: immediately

### Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 661 N-RA is recommended.

knitter-switch, May 2015



Oliver Kluj

Technical Director