## knitter-switch

## **Discontinuation of Products**

Products affected:

MSP 101 A, MSP 101 AB, MSP 101 A-RA

Effectivity date:

after current stock is sold

Details:

Due to worn-out tools the production of these pushbuttons is discontinued.

There is no direct replacement.

Our suggestions (in above order) are MZP 1 D, MZP 1 DB, MZP 1 D-RA.

knitter-switch, June 2022

Oliv Uly

Oliver Kluj

**Technical Director**