knitter-switch

Discontinuation of Products

Products affected: R 1275, RR 775, S 675, SCHLITZM.SCHWAR

Effectivity date:

after current stock is sold

Details:

Due to decreasing demand the production of these parts is discontinued.

We strongly recommend not to use these parts for new designs.

Please contact our local sales in case of ongoing demand.

knitter-switch, August 2022

Oliv Uluj

Oliver Kluj Technical Director