knitter-switch

## **Discontinuation of Products**

Product affected: SPA 106 D, SPA 106 F, SPA 206 N, SPA 206 R,

> SPW 106 D, SPW 106 F, SPW 206 N, SPW 206 R,

and the above, followed by B or G the above, followed by -PC or –WW the above, followed by B-PC or B-WW or G-PC or B-WW

Effective date:

after current stock is sold out

Details:

Due to bankruptcy of one of our subcontracting spare-part suppliers we are forced to remove these components from our range of products.

Our sales people will help you to find a replacement in another of our product lines. We recommend considering MPA series (for SPA) and MPE (for SPW) for replacement.

knitter-switch, June 2009

Mut allei

Oliver Kluj Technical Director