## knitter-switch

## **Product-Discontinuation Notice**

Affected products:

TSE 12 S, TSE 12 S-1, TSSE 12 S

Effective date:

after current stock is sold out

## Details:

Due to problems with components supplied by sub-contractors the production of these switch models stopped.

For replacement we recommend TSE 21495 S, TSE 21495 S-1 and TSSE 21495 S which come with same PCB-layout, similar dimensions and increased number of cycles (from 1 Mio to 5 Mio cycles).

knitter-switch, October 2020

Oliv My

Oliver Kluj

**Technical Director**