knitter-switch

Discontinuation of Products

Affected Products:

ASE 1 D RA-1, ASE 1 E RA-1

ASE 2 D RA-1, ASE 2 E RA-1

ASL 1 D RA-1, ASL 1 E RA-1 ASL 2 D RA-1, ASL 2 E RA-1

Effective date:

immediately

Details:

Due to lack of demand the production of the option "-1" has been stopped.

For replacement we suggest ASE standard models and gold-finished models of MSS 3000 series.

knitter-switch, July 2013

Oliv Uly

Oliver Kluj

Technical Director