## knitter-switch

## **Discontinuation of Products**

Products affected:

MFP 461 N, MFP 461 N-2MM, MFP 461 N-GRU

Effectivity date:

after coming lot is sold

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, MFP 421 N is recommended. Data-sheet see next page.

knitter-switch, February 2013

Oliv Uluj

Oliver Kluj Technical Director

## knitter-switch

