

knitter-switch

Discontinuation of Products

Products affected: MFPP 130 RA slide-switch

Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

For replacement, SMT-model MMSP 132 is recommended.

knitter-switch, February 2012



Oliver Kluj

Technical Director