

knitter-switch

Discontinuation of Products

Products affected: MFS 201 N-RT

Effectivity date: After current stock is sold out

Details:

Due to lack of demand production is discontinued.

For replacement consider use of MFS 201 N-SW, which has a black slider instead of a red one.

knitter-switch, July 2016



Oliver Kluj

Technical Director