

Discontinuation of LD 531

Product affected: LD 531

Effective date: after current stock is sold out

Details:

As replacement for this discontinued part, LD 532 was new introduced.

knitter-switch, August 2008

Olur allei

Oliver Kluj