

knitter-switch


Product Change Notice P12-2019

Products affected: DRS 50010-8.6, DRS 50016-8.6, DRS 50110-8.6

Effectivity date: After current stock is sold out

Details:

To prevent increase of delivery delay, switch position display and part number marking is changed from pad print to laser print. This change is not affecting any other features or specification of the components.




Left hand side: pad print

Right hand side: laser marking

(Picture for reference only – there will be no change of appearance of switch housing and other parts).

knitter-switch - Baldham, November 2019



Oliver Kluj
Technical Director