

knitter-switch







Product Change Notice P11-2022

Products affected: MERP 12-12P126GR, MERP 12-12P126M9GR
MERP 12-24118.5M, MERP 12-24126GR
MERP 12-24126M, MERP 12-24126M9BG
MERP 12-24126M9GR, MERP 12-24225GR
MERP 12-24225M, MERP 12-24225M9GR
MERP 12-24225OB, MERP 12-24N225M

Effectivity date: from next production lot


Details:

In order to strengthen the mechanical stability and reliability, the design of the base has been improved. This leads to a 0.3 mm higher case, and correspondingly to an increase of the total height by 0.3 mm. See illustration:

Sleeve bushing		 <p>The thickness is 7mm</p>	 <p>The thickness is 7.3mm Increasing 0.3mm</p>
Thread bushing		 <p>The thickness is 7.5mm</p>	 <p>The thickness is 7.8mm Increasing 0.3mm</p>

Please ask your sales contact for updated data-sheets or find it on our website.

knitter-switch - Baldham, October 2022



Oliver Kluj
Technical Director