knitter-switch

Product Change Notice P04-2023

Products affected: SBP 8002, SBP 8002 T, SBP 8004, SBP 8004 T, SBP 8006,

SBP 8006 T, SBP 8008, SBP 8008 T, SBP 8010, SBP 8010 T SBP 8102, SBP 8102 T, SBP 8104, SBP 8104 T, SBP 8106, SBP 8106 T, SPB 8108, SBP 8108 T, SBP 8110, SBP 8110 T,

SBP 8208 T, SBP 8304, SBP 8304 T, SBP 8308


Effectivity date:

after current stock is sold


Details:

In course of move from manual to automatic assembling a design improvement and the change from pad- to laser-print will be introduced.

There are no relevant changes in dimensions and specification, data-sheets are still valid.



Contact is simplified
Fixation of contact is improved



old pad-print I

new laser-marking

knitter-switch - Baldham, May 2023

Oliver Kluj

Technical Director