

knitter-switch

Product-Change Notification P6-2019


Products affected: MPBS 42H01-F14, MPBS 42H01-F20, MPBS 42H01L-F14
MPBS 42H01L-F18B, MPBS 42H01L-F20

Effective date: after current stock is sold out

Details:

For standardization reasons the material of upper case part was changed from ABS to Phenolic Resin.

This change is not affecting performance, spec or any other detail of the switch.



Front: old version

Background: new version

Knitter-switch, May 2019

Oliver Kluj
Technical Director