## knitter-switch

## **Product Change Notification**

## Change Of Welding Of Housing Parts

Products affected: DHS 901, DHS 901 NF, DHS 901 J, DHS 901 K

DHS 902, DHS 902 NF, DHS 902-1

DHS 902-1 NF, DHS 902 J, DHS 902 K  $\,$ 

DHS 904, DHS 904 NF, DHS 904 J, DHS 904 K DHS 906, DHS 906 NF, DHS 906 J, DHS 906 K DHS 908, DHS 908 NF, DHS 908 J, DHS 908 K DHS 910, DHS 910 NF, DHS 910 J, DHS 910 K

DHS 912, DHS 912 NF, DHS 912 K

Effective date:


after stock-clearance

Details:


Up to now the lid was inserted into a cut-out of the base part and ultrasonic welded.

To increase the robustness the lid was now changed to an upper case part with same crosssection as the base.

Due to this, the welding line moves towards the side walls. This allows a more aligned and stable welding quality.



up to now



from now on

knitter-switch, September 2013

This Why

Oliver Kluj

**Technical Director**