

knitter-switch


Product Change Notification

Affected products: DRR 60004, followed by -1 or -1H or -1CH
DRR 60010, followed by -1 or -1H or -1CH
DRR 60016, followed by -1 or -1H or -1CH
DRR 60104, followed by -1 or -1H or -1CH
DRR 60110, followed by -1 or -1H or -1CH
DRR 60116, followed by -1 or -1H or -1CH
DRR 61004, followed by -1 or -1H or -1CH
DRR 61010, followed by -1 or -1H or -1CH
DRR 61016, followed by -1 or -1H or -1CH
DRR 61104, followed by -1 or -1H or -1CH
DRR 61110, followed by -1 or -1H or -1CH
DRR 61116, followed by -1 or -1H or -1CH

Effective date: from production April 2012

Details:


The shape of the back part of the case was modified to allow more effective PCB design.
There are no other changes on these products.
Several data-sheets were amended due to standardization of technical data.



Up to now: large protrusion

From now on: small protrusion

knitter-switch, April 2012



Oliver Kluj
Technical Director