

Product Change Notification

Product affected: MMP 131 R

Effective date: May 2010

Details:

In order to improve soldering conditions with regard to lead-free processing (up to 260°C) the switch was redesigned.

This caused smaller modification that will not affect usability.

For details see data sheet.

The revised version is marked by blue actuator (previous: white) and will be delivered from May 2010.

knitter-switch, April 2010



Oliver Kluj
Technical Director