

Product Change Notification

Product affected: MPG 106 D, MPG 106 DB, MPG 106 DG
MPG 106 D-PC, MPG 106 DB-PC, MPG 106 DG-PC
MPG 106 F, MPG 106 FB, MPG 106 FG
MPG 106 F-PC, MPG 106 FB-PC, MPG 106 FG-PC

MPG 206 N, MPG 206 NB, MPG 206 NG
MPG 206 N-PC, MPG 206 NB-PC, MPG 206 NG-PC
MPG 206 R, MPG 206 RB, MPG 206 RG
MPG 206 R-PC, MPG 206 RB-PC, MPG 206 RG-PC

MPG 306 D, MPG 306 DB, MPG 306 DG
MPG 306 D-PC, MPG 306 DB-PC, MPG 306 DG-PC
MPG 306 F, MPG 306 FB, MPG 306 FG
MPG 306 F-PC, MPG 306 FB-PC, MPG 306 FG-PC

MPG 406 N, MPG 406 NB, MPG 406 NG
MPG 406 N-PC, MPG 406 NB-PC, MPG 406 NG-PC
MPG 406 R, MPG 406 RB, MPG 406 RG
MPG 406 R-PC, MPG 406 RB-PC, MPG 406 RG-PC

Effective date: after current stock is sold out

Details:

For several reasons a product redesign was necessary.
Switching mechanism and case design was updated.
The moulded-in terminals were replaced by epoxy-sealed terminals.
The print/marketing is now more durable.
Smaller modification in dimensions was made for unification reasons.

All modification was made in a way that applicability, key features, endurance and reliability was not affected.

For more details see data-sheets.

knitter-switch, June 2009



Oliver Kluj
Technical Director