

Product Change Notification

Affected product: MPS 103 F, MPS 103 FB
 MPS 103 F-PC, MPS 103 FB-PC
 MPS 203 R, MPS 203 RB
 MPS 203 R-PC, MPS 203 RB-PC

Effective date: after current stock is sold out

Bushing material change: old – brass, nickel-plated
 new – zinc, die-casted

Details:
Material is changed for standardization reasons.

Due to material characteristics of zinc, the shape of the bushing/sleeve changes marginally.

When using the supplied standard mounting accessory, new bushing type switch appearance is same as the old one.

Separate drawing is available on demand.

The changing will not affect any electrical, mechanical or other properties.

knitter-switch, January 2011



Oliver Kluj
Technical Director