

# knitter-switch


## Product Change Notification

Products affected: DBP 9006, DBP 9007, DBP 9008, DBP 9010, DBP 9012  
DBP 9006F, DBP 9007F, DBP 9008F, DBP 9010F, DBP 9012F  
DBP 9106, DBP 9107, DBP 9108, DBP 9110, DBP 9112  
DBP 9106THR, DBP 9107THR, DBP 9108THR, DBP 9110THR  
DBP 9112THR

SBP 9006, SBP 9007, SBP 9008, SBP 9010, SBP 9012  
SBP 9006T, SBP 9007T, SBP 9008T, SBP 9010T, SBP 9012T  
SBP 9106, SBP 9107, SBP 9108, SBP 9110, SBP 9112  
SBP 9106T, SBP 9107T, SBP 9108T, SBP 9110T, SBP 9112T  
SBP 9106TF, SBP 9107TF, SBP 9108TF, SBP 9110TF, SBP 9112TF  
SBP 9106TG, SBP 9107TG, SBP 9108TG, SBP 9110TG  
SBP 9112TG

Effective date: after current stock is sold out

Details: To improve the thermal stability of the cases, stiffeners were added.



This modification slightly affects the appearance. There is no change in dimensions, specification or any other technical data. Individual drawings will not be revised immediately - the modification will be introduced to the drawings together with the next update.

Knitter-switch, December 2012

Oliver Kluj  
Technical Director