

## Product Change Notification

Product affected: SBP 9200  
Change from tin plated contacts to gold plated contacts

Effective date: August 2006

### Details:

Due to a too high contact resistance during the final quality control we decided to change the contact material of the SBP 9200 series from tin to gold.

Please note that the part number suffix will change from "TK" and "JTK" to "T" and "JT"

The following part numbers are affected:

<u>Tin plated P/N</u>	<u>Gold plated P/N</u>
SBP 9202 JTK	SBP 9202 JT
SBP 9203 JTK	SBP 9203 JT
SBP 9204 JTK	SBP 9204 JT
SBP 9205 JTK	SBP 9205 JT
SBP 9206 JTK	SBP 9206 JT
SBP 9208 JTK	SBP 9208 JT
SBP 9210 JTK	SBP 9210 JT
SBP 9208 TK	SBP 9208 T
SBP 9210 TK	SBP 9210 T

knitter switch, August 2006

