

knitter-switch

Discontinuation of Products


Products affected: MFP 127 S-RA slide-switch

Effectivity date: immediately

Details:

Due to lack of demand and worn-out tools continuation of production becomes uneconomical.

knitter-switch, May 2018



Oliver Kluj

Technical Director