## knitter-switch

## **Discontinuation of Products**

Affected products:

APE 1 F RA-1, APE 2 F RA-1

Effective date:

immediately

Details:

Due to lack of demand the production of the option "-1" has been stopped.

For replacement we suggest APE standard models and FP- and TSP-series.

knitter-switch, July 2013

Oliv Uluj

Oliver Kluj Technical Director