

Product Change Notification

Product affected: MFP 2320
 MFP 2520
 MFP 2620

Effective date: after current stock is sold out

Plating modification: old – Zinc-plating, new – Nickel-plating

Details:

According to the decreasing demand of Zinc-plated surfaces, the cost for plating increases.

Therefore we will use Nickel-plating.

The changing will not modify any electrical, mechanical or other properties.

knitter-switch, September 2008



Oliver Kluj
Engineering