knitter-switch

Product-Change Notification

Products affected: DBS 2002, DBS 2003, DBS 2004, DBS 2005, DBS 2006,

DBS 2007, DBS 2008, DBS 2009, DBS 2010, DBS 2012, DBS 2102, DBS 2103, DBS 2104, DBS 2105, DBS 2106,

DBS 2107, DBS 2108, DBS 2108 F, DBS 2108 SW,

DBS 2109, DBS 2110, DBS 2112

Effective date:


after current stock is sold out


Epoxy sealing of terminals

Details:

To improve safety against flux entry, the terminals will be sealed with epoxy from now on. Additionally the case is optimized to support the sealing safety.

The change of case allows to distinguish the non-sealed and the sealed version easily.





Up to now

From now on

knitter-switch, November 2017

Oliv Uly

Oliver Kluj

Technical Director