

# knitter-switch


## Product Change Notice

Products affected: DRS 61110-2.2

Effectivity date: After current stock is sold out

### Details:

In order to achieve a better washability additionally to the specified IP67 protection, the gasket between rotor and upper case part (silicone-rubber O-ring) is improved.



The last date-code/ lot-number of parts with old O-ring is 2019-11-27 / K19019.  
All later date-codes / subsequent lot-numbers will come with new O-Ring

This change is not affecting any spec or feature displayed in the switch data-sheet.

knitter-switch - Baldham, November 2019

Oliver Kluj  
Technical Director