knitter-switch

Product Change Notification

Products affected: DBS 3001, DBS 3002, DBS 3003, DBS 3004, DBS 3005

DBS 3006, DBS 3007, DBS 3008, DBS 3009, DBS 3010

DBS 3012

DBS 3101, DBS 3102, DBS 3103, DBS 3104, DBS 3105 DBS 3106, DBS 3107, DBS 3108, DBS 3109, DBS 3110

DBS 3112

Effective date:

from December 2010

Details:

After several trials we have found that these models are unsuitable for potting of pcb if certain casting compounds are used.

Therefore, the feature "suitable for potting" was removed from the specification.

Models applicable to casting/potting are marked by the appendix –SL from now on. Use only cold-curing compounds!

Example for ordering code: DBS 3108-SL

Any other technical data or specification is not affected by this.

Knitter-switch, December 2010

Oliv Uly

Oliver Kluj

Technical Director