knitter-switch

Product- Change Notice

Product affected:

MMP 121 R

Valid from:

immediately

Details:

The component was revised.

The appearance and technical data remain.

The PCB layout recommendation was defined more detailed.

See following page for new version and modifications compared to previous version.

knitter-switch, November 2012

Oliv Uly

Oliver Kluj

Technical Director

knitter-switch

