

Product Change Notification

Product affected: MTG 306 D, MTG 306 DB, MTG 306 DG
MTG 306 D-PC, MTG 306 DB-PC, MTG 306 DG-PC
MTG 306 E, MTG 306 EB, MTG 306 EG
MTG 306 E-PC, MTG 306 EB-PC, MTG 306 EG-PC
MTG 306 F, MTG 306 FB, MTG 306 FG
MTG 306 F-PC, MTG 306 FB-PC, MTG 306 FG-PC
MTG 306 G, MTG 306 GB, MTG 306 GG
MTG 306 G-PC, MTG 306 GB-PC, MTG 306 GG-PC
MTG 306 H, MTG 306 HB, MTG 306 HG
MTG 306 H-PC, MTG 306 HB-PC, MTG 306 HG-PC

MTG 406 N, MTG 406 NB, MTG 406 NG
MTG 406 N-PC, MTG 406 NB-PC, MTG 406 NG-PC
MTG 406 P, MTG 406 PB, MTG 406 PG
MTG 406 P-PC, MTG 406 PB-PC, MTG 406 PG-PC
MTG 406 R, MTG 406 RB, MTG 406 RG
MTG 406 R-PC, MTG 406 RB-PC, MTG 406 RG-PC
MTG 406 S, MTG 406 SB, MTG 406 SG
MTG 406 S-PC, MTG 406 SB-PC, MTG 406 SG-PC
MTG 406 T, MTG 406 TB, MTG 406 TG
MTG 406 T-PC, MTG 406 TB-PC, MTG 406 TG-PC

Effective date: after current stock is sold out

Details:

For several reasons a product redesign was necessary.
Switching mechanism and case design was updated.
The moulded-in terminals were replaced by epoxy-sealed terminals.
The print/marketing is now more durable.
Smaller modification in dimensions was made for unification reasons.

All modification was made in a way that applicability, key features, endurance and reliability was not affected.

For more details see data-sheets.

knitter-switch, June 2009



Oliver Kluj
Technical Director