

knitter-switch

Product Change Notification

Affected products: TMSE 10 J-RA


Effective date: from production January 2012

Details:


In the course of continuously product improvement the design of the carrier tape pockets is changed. This will support the stable position of the component during pick&place by avoid of tilting of the component in the pocket.

All specifications and technical data remain unchanged.


Old: component may tilt back and forth




New: No tilting by support of knob




Old: component may tumble from left to right



New: No tumbling by tighter pocket



knitter-switch, December 2011



Oliver Kluj
Technical Director