


knitter-switch

Product Change Notice P2024-03


Products affected: DBS/SBP/SBS 1000/1100 series
details see following page

Effectivity date: from manufacturing date September 30, 2024

Details:
in order to improve environmental compliance the print method is changing from pad print to laser marking



old version



new version

There is no change of dimensions, electrical and mechanical properties or other specification and packing.

knitter-switch - Baldham, May 2024

A handwritten signature in black ink, reading "Oliver Kluj".

Oliver Kluj
Technical Director

knitter-switch

Affected part numbers:

DBS 1001	DBS 1002	DBS 1003
DBS 1004	DBS 1005	DBS 1006
DBS 1007	DBS 1008	DBS 1009
DBS 1010		
DBS 1101	DBS 1102	DBS 1102 S1
DBS 1103	DBS 1103 S	DBS 1103 S1
DBS 1104	DBS 1104 S1	DBS 1105
DBS 1106	DBS 1106 S1	DBS 1107
DBS 1107 S1	DBS 1108	DBS 1108 S1
DBS 1109	DBS 1110	DBS 1110 S1
DBS 1112		
SBP 1102 T	SBP 1104 T	SBP 1106 T
SBS 1001	SBS 1001 T	SBS 1001 TG
SBS 1001 T-WILO	SBS 1002	SBS 1002 T
SBS 1002 T L	SBS 1002 T -ON	SBS 1002 TG
SBS 1002 TG-NF	SBS 1002 TG-ON	SBS 1002 T-NF
SBS 1003	SBS 1003 T	SBS 1003 T -ON N.F.
SBS 1003 T-V-ON N.F.	SBS 1004	SBS 1004 T
SBS 1004 TG	SBS 1004 T-IS	SBS 1004 T-ON
SBS 1005	SBS 1005 T	SBS 1006
SBS 1006 T	SBS 1006 TG	SBS 1006 TG-ON
SBS 1007	SBS 1007 T	SBS 1007 T N.F.
SBS 1008	SBS 1008 ON	SBS 1008 T
SBS 1008 T G	SBS 1008 T G-ON	SBS 1009
SBS 1009 T	SBS 1009-2 T	SBS 1010
SBS 1010 T	SBS 1010 T G	SBS 1012 T
SBS 1101 T	SBS 1102 T	SBS 1103 T
SBS 1104 T	SBS 1106	SBS 1106 T
SBS 1107	SBS 1108 T	SBS 1109
SBS 1110	SBS 1112	SBS 1112 T